



Winifred to Big Sandy Corridor Study

Final Report



Prepared for



Chouteau County



Fergus County

Prepared by

DKS Associates
TRANSPORTATION SOLUTIONS

May 2011

Winifred to Big Sandy Corridor Study

Final Report

May 2011



Prepared By:

DKS Associates, Inc.



Table of Contents

- 1.0 EXECUTIVE SUMMARY 1**
- 1.1 INTRODUCTION 1
- 1.2 EXISTING AND FUTURE CONDITIONS..... 1
- 1.3 CONSULTATION AN COORDINATION 3
- 1.4 CORRIDOR NEEDS 4
- 1.5 IMPROVEMENT OPTIONS 4
- 1.6 FUNDING..... 5
- 1.7 CONCLUSION..... 6
- 2.0 INTRODUCTION..... 7**
- 2.1 STUDY PURPOSE 7
- 2.2 STUDY BACKGROUND..... 7
- 2.3 STUDY PROCESS..... 9
- 3.0 EXISTING AND FUTURE CONDITIONS10**
- 3.1 ROADWAYS..Pg10-12 Pg13-15 Pg16-18 Pg19-21 Pg22-24 Pg25-26 Pg27-29.....10
- 3.2 ENVIRONMENTAL SETTING 30
- 3.3 FUTURE TRANSPORTATION CONDITIONS 35
- 4.0 CONSULTATION AND COORDINATION39**
- 4.2 INFORMATIONAL MEETINGS..... 40
- 4.3 STAKEHOLDER INTERVIEWS 42
- 4.4 RESOURCE AND OTHER AGENCY CONSULTATION 43
- 5.0 NEEDS AND OBJECTIVES45**
- 6.0 IMPROVEMENT OPTIONS46**
- 6.1 ISSUE LOCATIONS 46
- 6.3 EVALUATION OF IMPROVEMENT OPTIONS 50
- 6.4 PROJECT BUNDLES..... 51
- 6.5 PLANNING LEVEL COST ESTIMATESPage 52-53 Page 54-56 Page 57-58 Page 59..... 59
- 6.6 IMPLEMENTATION SCENARIOS 60
- 6.7 PRIORITIZATION OF PROJECT BUNDLES 61
- 7.0 FUNDING67**
- 8.0 CONCLUSION70**



List of Figures

Figure 1 Corridor Location Map..... 8

Figure 2 Corridor Study Area Map..... 11

Figure 3 Crashes by Severity, Type, and Cause..... 13

Figure 4 Existing AADT 14

Figure 5 Crash Conditions 15

Figure 6 Roadway Width..... 18

Figure 7 Terrain Type 19

Figure 8 Roadway Sight Distance..... 21

Figure 9 Horizontal Curves..... 23

Figure 10 Grades 24

Figure 11 Roadside Hazard Rating 26

Figure 12 Intersections 28

Figure 13 Other Modes..... 29

Figure 14 Future Traffic Growth 36

Figure 15 2030 AADT 37

Figure 16 Narrow Roadway Near Murphy Lane (RP 30.8)..... 47

Figure 17 Poor Roadway Surface Near Berlinger Rd. (RP 68.7)..... 48

Figure 18 Vertical Curve Near RP 35.7..... 48

Figure 19 Horizontal Curve Near Heggem Ln. (RP 33.6)..... 49

Figure 20 Severe Side Slope Near Murphy Ln. (RP 30.8)..... 49

Figure 21 Restricted Intersection Sight Distance at Stulc Ln. (RP 32.4) 50

Figure 22 Skewed Intersection at Eight Mile Bench Rd. (RP 59.4) 50

Figure 23 Proposed Project Bundle Locations 53

Figure 24 Vertical Curves Near Tobin Ln. (RP 28.6) 54

Figure 25 Combined Horizontal/Vertical Curve and Roadside Obstruction
South of Stulc Ln. (RP 31.5)..... 54





List of Figures (continued)

Figure 26	Combined Horizontal/Vertical Curves. (RP 36.9).....	55
Figure 27	Claggett Hill (RP 46.1)	56
Figure 28	S-curve Near Chip Creek. (RP 53.2).....	56
Figure 29	Hill Near Jappe Trail (RP 55.1).....	57
Figure 30	The “Wide Spot” Near Hopp Rd. (RP 73.0)	58
Figure 31	Curve at Lone Tree Trail (RP 82.8)	59
Figure 32	Proposed Project Bundle Rankings	66





List of Tables

Table 1	Stakeholder Interviewees	43
Table 2	General Improvement Types	47
Table 3	Improvement Option Screening Criteria	51
Table 4	Proposed Project Bundle Locations	52
Table 5	Cost Estimates.....	61
Table 6	Proposed Project Bundle Rankings – Spot Improvements Only.....	64
Table 7	Proposed Project Bundle Rankings – Reconstruct/Rehabilitate to Gravel.....	64
Table 8	Proposed Project Bundle Rankings – Reconstruct/Rehabilitate to Pavement.....	65





List of Appendices

- Appendix A Consultation and Coordination (pages 7 – 106 on CD)
- Appendix B Existing and Future Conditions Report (on CD)
- Appendix C Environmental Scan (on CD)
- Appendix D Improvement Options (on CD)
- Appendix E Memorandum of Understanding (on CD)